

PO Box 5, Morley, LS27 0QP Page Nepshaw Lane South, Morley, Leeds Tel 0113 253 0241 Fax 0113 252 7029 Head of Laboratory G. Briggs C. Text ATI

Client:	Camira Fabrics Ltd Meltham Mills Meltham West Yorkshire HD9 4AY
Entry No:	48300
Date received:	04/10/2011
Client's Description:	Sample of fabric Intervene Plain
	TEST REPORT
Test Required:	TEST REPORT Flammability in accordance with BS 5852 ignition source 5
Test Required: Pre-treatment:	
•	Flammability in accordance with BS 5852 ignition source 5 Water soaking in accordance with Annex E in BS 5852 : 2006 followed by line
Pre-treatment:	Flammability in accordance with BS 5852 ignition source 5 Water soaking in accordance with Annex E in BS 5852 : 2006 followed by line drying

The following test results relate only to the ignitability of the combination of upholstery composites under the particular conditions of test. They are not intended as a means of assessing the full potential fire hazard of the materials in use.

Ignition Source	Observations	Result
5 (Wood Crib)	1 st Determination	PASS
	Flaming ceased within the specified 10 minute period after	
	ignition of the crib and no progressive smouldering occurred.	
	2 nd Determination	
	Flaming passed through the full thickness of the composite.	

Note: A 35 kg/m³ CMHR Foam (Carpenters RX36-125) was used as the filling.

-----End of Document-----

This is hereby certified to be a correct return of the tests made of the items referred to herein.



Briggs

G Briggs Head of Laboratory 13 October 2011

- Unless instructed otherwise by the client sample remnants will be disposed of after 28 days
 Test marked (*) in this certificate are not included in the UKAS Accreditation Schedule for this Laboratory.
- Opinions and interpretations expressed herein are outside the scope of UKAS accreditation.
 This Certificate relates only to the sample received and, unless that sample has been drawn by the staff of this laboratory, or its agent, and endorsed accordingly, any application of the result to a bulk quantity or other material is entirely the responsibility of the client.

